



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0002

Policy / Contract Name: COSTESSEY PARISH COUNCIL

Name of Occupier: COSTESSEY PARISH COUNCIL

Address: LONGWATER LANE OLD COSTESSEY NORWICH NR8 5AH

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
No 09	Not Applicable Not Known Multi Activity Units (playgrounds) 6 - 10 activities with slide. Adventure Playgrounds Ltd 2010	Toddler Area	Adventure Playgrounds Ltd 2010
94310478/23	(a) None. (b) The hole on the top of the log bridge post should be suitably filled.	None.	08/10/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0002

Policy / Contract Name: COSTESSEY PARISH COUNCIL

Name of Occupier: COSTESSEY PARISH COUNCIL

Address: LONGWATER LANE OLD COSTESSEY NORWICH NR8 5AH

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
FA 05	Not Applicable Not Known Adult Fitness Equipment:- Cycle machine 2011	Fitness area	2011
108530478/22	(a) None. (b) The bearing shield on the right pedal has become displaced and should be repaired.	None.	08/10/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0002

Policy / Contract Name: COSTESSEY PARISH COUNCIL

Name of Occupier: COSTESSEY PARISH COUNCIL

Address: LONGWATER LANE OLD COSTESSEY NORWICH NR8 5AH

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
FA 11	Not Applicable TG0604A Adult Fitness Equipment:- Leg press(b) Outdoor Gym Co 2011	Fitness area	Outdoor Gym Co 2011
108590478/22	(a) None. (b) The seat restraint chain bracket is worn and should be repaired.	None.	08/10/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0002

Policy / Contract Name: COSTESSEY PARISH COUNCIL

Name of Occupier: COSTESSEY PARISH COUNCIL

Address: LONGWATER LANE OLD COSTESSEY NORWICH NR8 5AH

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
No 17	Not Applicable GXY86521 Playground Equipment:- Spinning Pole. Kompan 2011	Adventure Area	Kompan 2011
129620478/20	(a) None. (b) There is lateral movement in the bearing at the lower attachment point and this play should be eliminated.	None.	08/10/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0002

Policy / Contract Name: COSTESSEY PARISH COUNCIL

Name of Occupier: COSTESSEY PARISH COUNCIL

Address: LONGWATER LANE OLD COSTESSEY NORWICH NR8 5AH

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
No 21	Not Applicable Not Known Nest Swing 2012	Adventure Area	2012
135000478/19	(a) None. (b) There are exposed wire ropes in the centre of the swing and these should be suitably covered.	None.	08/10/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0002

Policy / Contract Name: COSTESSEY PARISH COUNCIL

Name of Occupier: COSTESSEY PARISH COUNCIL

Address: LONGWATER LANE OLD COSTESSEY NORWICH NR8 5AH

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
No 20	Not Applicable Not Known Multi Activity Units (playgrounds) 11+ activities Kompan 2012	Adventure Area	Kompan 2012
134990478/19	(a) None. (b) The four missing nut covers at the top helical post entry should be replaced. The extended bolt at the bottom of the parallel bars should be renewed.	None.	08/10/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0001

Policy / Contract Name: COSTESSEY PARISH COUNCIL

Name of Occupier: COSTESSEY PARISH COUNCIL

Address: BRECKLAND ROAD NEW COSTESSEY NORWICH NR5 0RW

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
No 17	Not Applicable T2290 Nest Swing A E Evans 2015	Adventure Area	A E Evans 2015
195420478/13	(a) None. (b) There are exposed wire ropes on the suspension ropes and these should be suitably covered.	None.	08/10/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0001

Policy / Contract Name: COSTESSEY PARISH COUNCIL

Name of Occupier: COSTESSEY PARISH COUNCIL

Address: BRECKLAND ROAD NEW COSTESSEY NORWICH NR5 0RW

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
No 18	Not Applicable Not Known Round-a-bout Not Known 2016	Toddler Area	Not Known 2016
203160478/12	(a) None. (b) The bearings are noisy and stiff and should be freed.	None.	08/10/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0001

Policy / Contract Name: COSTESSEY PARISH COUNCIL

Name of Occupier: COSTESSEY PARISH COUNCIL

Address: BRECKLAND ROAD NEW COSTESSEY NORWICH NR5 0RW

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
No 16	Not Applicable Not Known Multi Activity Units (playgrounds) 6 - 10 activities - "Parkour" fitness / climbing unit. Park Leisure 2011	Parkour Area	Park Leisure 2011
119390478/21	(a) None. (b) The missing nut covers should be replaced. The render has broken away from the concrete section and this should be repaired.	None.	08/10/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0001

Policy / Contract Name: COSTESSEY PARISH COUNCIL

Name of Occupier: COSTESSEY PARISH COUNCIL

Address: BRECKLAND ROAD NEW COSTESSEY NORWICH NR5 0RW

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
No 15	Not Applicable CAR1859/01 Playground Equipment:- - Basket ball post Not Known	Park	Not Known
41130331/41	(a) None. (b) The damaged back board should be renewed.	No net fitted.	08/10/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0001

Policy / Contract Name: COSTESSEY PARISH COUNCIL

Name of Occupier: COSTESSEY PARISH COUNCIL

Address: BRECKLAND ROAD NEW COSTESSEY NORWICH NR5 0RW

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
GPA Fitness	None Not Applicable General Play Area including perimeter fencing and benches. Not Known	Fitness Area	Not Known
23163363/1	(a) None. (b) The scalloped out aread under one bench should be suitably filled.	None.	08/10/2021

The equipment has been examlned in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0001

Policy / Contract Name: COSTESSEY PARISH COUNCIL

Name of Occupier: COSTESSEY PARISH COUNCIL

Address: BRECKLAND ROAD NEW COSTESSEY NORWICH NR5 0RW

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
No 06	Not Applicable Not Known Multi Activity Units (playgrounds) 2 - 5 activities - Tyre swings & tram track	Adventure Area	
918318203/46	(a) None. (b) The suspension chains are worn and should be renewed. The distorted upper chain links to the tyre swings should be renewed.	None.	08/10/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0001

Policy / Contract Name: COSTESSEY PARISH COUNCIL

Name of Occupier: COSTESSEY PARISH COUNCIL

Address: BRECKLAND ROAD NEW COSTESSEY NORWICH NR5 0RW

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
No 05	Not Applicable Not Known Multi Activity Units (playgrounds) 2 - 5 activities - Log swings, tram track & balance beam. Not Known	Adventure Area	Not Known
918308203/46	(a) None. (b) The tram track chains are worn and dragging lower than designed and this should be rectified.	None.	08/10/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0001

Policy / Contract Name: COSTESSEY PARISH COUNCIL

Name of Occupier: COSTESSEY PARISH COUNCIL

Address: BRECKLAND ROAD NEW COSTESSEY NORWICH NR5 0RW

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
No 02	Not Applicable Not Known Playground Equipment:- Stepping logs (4) Not Known	Adventure Area	Not Known
918278203/46	(a) None. (b) The cross-sectional area of the top of one log is diminished and should be replaced.	None.	08/10/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0001

Policy / Contract Name: **COSTESSEY PARISH COUNCIL**
Name of Occupier: **COSTESSEY PARISH COUNCIL**
Address: **BRECKLAND ROAD NEW COSTESSEY NORWICH NR5 0RW**

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
No 13	Not Applicable Not Known Slide Hirst	Toddler Area	Hirst
918238203/46	(a) None. (b) The surface corrosion on the ladder frame should be cleaned and treated accordingly.	None.	08/10/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0001

Policy / Contract Name: COSTESSEY PARISH COUNCIL

Name of Occupier: COSTESSEY PARISH COUNCIL

Address: BRECKLAND ROAD NEW COSTESSEY NORWICH NR5 0RW

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
No 12	Not Applicable Not Known Rocking Horse Wickstead	Toddler Area	Wickstead
918228203/46	(a) None. (b) The surface corrosion should be cleaned and treated accordingly. The offside under runner beam is rotten and should be renewed.	None.	08/10/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0001

Policy / Contract Name: COSTESSEY PARISH COUNCIL

Name of Occupier: COSTESSEY PARISH COUNCIL

Address: BRECKLAND ROAD NEW COSTESSEY NORWICH NR5 0RW

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
No 19	Not Applicable Not Known Multi Activity Units (playgrounds) 6 - 10 activities - Pirate Ship. NGF Play 2017	Toddler Area	NGF Play 2017
235900478/8	(a) None. (b) The missing nut covers should be replaced. The holes left by the removal of the fore mast should be suitably filled. The handrail above the ladder entry point has a hole and this should be suitably filled. The right post for the plank entry is loose and should be secured.	None.	08/10/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0003

Policy / Contract Name: COSTESSEY PARISH COUNCIL

Name of Occupier: COSTESSEY PARISH COUNCIL

Address: HUSENBETH CLOSE OLD COSTESSEY NR8 5EW

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
No 10	Not Applicable Not Known Playground Equipment:- Description Audio Book with Handwheel. Not Known	Open Area	Not Known
14693363/3	(a) None. (b) The damaged Handwheel Speaker cover should be repaired. Both posts are starting to rot at the bottom and this should be cleaned and treated accordingly.	None.	08/10/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0003

Policy / Contract Name: COSTESSEY PARISH COUNCIL

Name of Occupier: COSTESSEY PARISH COUNCIL

Address: HUSENBETH CLOSE OLD COSTESSEY NR8 5EW

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
No 6	Not Applicable Not Known Playground Equipment:- - Log Stilts (6)	Fenced Area	
213020478/11	(a) None. (b) Four lower stilt posts are rotting at the top and this should be suitably treated and filled. Four upper stilt posts are rotting at the top and this should be suitably treated and filled.	None.	08/10/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0003

Policy / Contract Name: COSTESSEY PARISH COUNCIL

Name of Occupier: COSTESSEY PARISH COUNCIL

Address: HUSENBETH CLOSE OLD COSTESSEY NR8 5EW

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
No 4	Not Applicable Not Known Playground Equipment:- -Wooden Tunnel.	Fenced Area	
213000478/11	(a) None. (b) One support post has a rotten hole at the top and this should be suitably treated and filled.	None.	08/10/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL2720032413000 Schedule: L0003

Policy / Contract Name: COSTESSEY PARISH COUNCIL

Name of Occupier: COSTESSEY PARISH COUNCIL

Address: HUSENBETH CLOSE OLD COSTESSEY NR8 5EW

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
GPA	Not Applicable Not Known General Play Area including fence, gates and bench.	Fenced Area	
212960478/11	(a) None. (b) The damaged perimeter fence uprights should be repaired. The entrance gate is not self-closing fully and should be repaired.	None.	08/10/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Christopher Sanders
Designation: Engineer Surveyor

Contact: c.sanders2@uk.zurich.com
Telephone: 07875 398 635

Date: 08/10/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.